

Fig. 2A




Fig.3




Fig.4




Fig.5B




Fig.5A





Fig.6







Fig.8




Fig.9




Fig.10






Fig.12B




Fig.12A




Fig.13




Fig.14




Fig.15B







Fig.15A







Top view of a circular component 100. It features a central hole 1a surrounded by concentric rings 42 and 43. Six bolt holes 17 are arranged in a circular pattern around the center. A reference numeral 18 points to the outer edge of the component. A bracket 15 indicates the outer boundary, and a reference numeral 16 points to the outer edge of the component.

Fig.19A




Fig.19B




Fig.20A




Fig.20B




Fig.21B




Fig.21A






Fig.24




Fig.25

